Message

From: Rick Grant [rgrant@oit.umass.edu]

Sent: 1/11/2011 3:25:12 PM

To: 'Lobik Stephen' [slobik@facil.umass.edu]

CC: 'Hanchett, James (DPH)' [James.Hanchett@state.ma.us]

Subject: RE: Morr I/Morr IV Second Floor Plans

We do have another issue in new Room N224 and that is Jack 2-1-25. That jack is located in another room so Leslie will be working on resolving the actual Jack number that should be there. Hopefully, that can be done so I can get the work order in the system. If 5-6604 could be located elsewhere in the room, that would help as well.

Richard J. Grant
Design Specialist/Customer Service
UMass Telecommunication Services
101 University Drive, Suite B1
Amherst, MA 01002-2376
413.545.2171

From: Lobik Stephen [mailto:slobik@facil.umass.edu]

Sent: Tuesday, January 11, 2011 8:07 AM

To: Rick Grant; Verdi Roxanne

Subject: RE: Morr I/Morr IV Second Floor Plans

Rick,

Attached is the approved plan with new room numbers in red.

Stephen

Stephen Lobik Capital Project Manager Facilities & Campus Planning Division University of Massachusetts

(T) 413-545-6516

(C)

(F) 413-545-3684

slobik@facil.umass.edu

From: Rick Grant [mailto:rgrant@oit.umass.edu]

Sent: Monday, January 10, 2011 4:06 PM

To: Verdi Roxanne **Cc:** Lobik Stephen

Subject: Morr I/Morr IV Second Floor Plans

Hi, Roxanne;

We're having issues with room numbering right where the two second floors meet for Morrill I & Morrill IV. Can you send me both floor plans? Thank you.

Rick

Richard J. Grant
Design Specialist/Customer Service
UMass Telecommunication Services
101 University Drive, Suite B1
Amherst, MA 01002-2376
413.545.2171